


## KREST THREE DEPARTURE

REDDING RGNL (RDD)  
REDDING, CALIFORNIA



NOTE: Chart not to scale.

**TAKEOFF RUNWAYS 12 and 16:** Turn left immediately after departure to intercept and proceed on the RDD R-355 to KREST DME Fix. Cross KREST DME Fix at or above 4000, thence on (transition) or (assigned route).

**TAKEOFF RUNWAYS 30 and 34:** Turn right immediately after departure to intercept and proceed on RDD R-355 to KREST DME Fix. Cross KREST DME Fix at or above 4000, thence on (transition) or (assigned route).

TOMAD TRANSITION (KREST3.TOMAD): From over KREST DME Fix on RDD 12 DME Arc counterclockwise to RDD R-217, thence on RDD R-217 to TOMAD INT.

## KREST THREE DEPARTURE

(KREST3.KREST) 30MAR95

REDDING, CALIFORNIA  
REDDING RGNL (RDD)

SW-2, 10 JUL 2025 to 07 AUG 2025