

⚠

Simultaneous approach authorized. Use of FD or AP required during simultaneous operations. LNAV procedure NA during simultaneous operations. Inop table does not apply to LPV all Cats. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below 7°C or above 54°C. For inop ALS, increase LNAV/VNAV all Cats visibility to 1½ SM and LNAV Cats C/D to 1½ SM.

MALSR

MISSED APPROACH:

Climb to 800 then climbing right turn to 4000 direct HUKUK and hold, continue climb-in-hold to 4000.

D-ATIS 135.0	MIAMI APP CON 133.775 285.6	FORT LAUDERDALE TOWER 119.3 257.8	GND CON 121.4	CLNC DEL 128.4	CPDLC
-----------------	--------------------------------	--------------------------------------	------------------	-------------------	-------

MISSED APCH FIX
4 NM

Procedure NA for arrival on FLL VOR/DME airway radials 013 CW 121.

ELEV 65	D	TDZE 7	<div><div><div>800</div><div>4000</div><div>HUKUK</div></div><div>VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 6°).</div><div></div><div></div></div>			
<div></div>			<div><div>1.7 NM</div><div>4.4 NM</div><div>6.3 NM</div></div>			
CATEGORY			A	B	C	D
LPV DA			257/40		250 (200-¾)	
LNAV/VNAV DA			581-1¼		574 (600-1¼)	
LNAV MDA			620/24	613 (600-½)	620-1⅓	613 (600-1⅓)
CIRCLING			680-1	615 (700-1)	800-2 735 (800-2)	800-2¼ 735 (800-2¼)

FORT LAUDERDALE, FLORIDA

Amdt 5A 25JAN24

FORT LAUDERDALE/HOLLYWOOD INTL (FLL)

26°04'N-80°09'W

RNAV (GPS) Y RWY 28R