

ILS or LOC RWY 5
ALBERT J. ELLIS (O.A.T.)

MALSR

MISSED APPROACH:
Climb to 600 then
climbing left turn to
2100 direct ELLAS
LOM/I-OAJ 7.4 DME
and hold.

ADF or DME REQUIRED

