

LOC/DME I-JVW 108.55 Chgn 22 (Y)	APP CRS 124°	Rwy Idg 5499 TDZE 241 Apt Elev 247
--	------------------------	---

ILS or LOC RWY 12

A When local altimeter setting not received, use Hawkins Fld altimeter setting: increase all DA 36 feet, all MDA 40 feet, S-LOC 12 Cat C and D visibilities $\frac{1}{4}$ mile, and Circling Cat C and D visibilities $\frac{1}{4}$ mile, increase FVSO fix minimums S-LOC 12 Cat C and D visibilities $\frac{1}{4}$ mile and Circling Cat C and D visibilities $\frac{1}{4}$ mile.

MISSED APPROACH: Climb to 800 then climbing left turn to 2900 on heading 316° and on MHZ VORTAC R-271 to CIGDA INT/I-JVW 14.6 DME and hold.

AWOS-3PT	JACKSON APP CON ★	UNICOM
118.675	125.25 319.2	123.0 (CTAF) 0

