

ILS or LOC RWY 23
AKRON-CANTON RGNI (CAK)

MISSED APPROACH: Climb to 2500 then climbing left turn to 3000 direct BSV VOR/DME and hold.

MSA ACO 25 NM

180°
360°

[3100] [ACO] [3600]

A 2048

HOLD 3000

(IF)
OCUGA INT
I-GGZ [13]

3000
205° (2.5)

025° 205° 054°

I-AF AKRON
114.4 ACO
Chan 91

Holding not required for arrivals on ACO VOR/DME airway radials 065 CW 123.

EGGII INT
I-GGZ [5.2]

ZERU INT
I-GGZ [1.2]

1321±
1427

R-008 R-019 R-030

A 1699 **A 2048**

LOCALIZER 108.3
I-GGZ
Chan 20

MISSED APCH FIX

BRIGGS
114.05 BSV
Chan 87(Y)

188°
R-188 -008°

EIVV 122.4 **TDZE 122.4**

114.05 BSV
Chan 87(Y)

ALTERNATE MISSED APPROACH FIX

MINER ACO [24.8]

114.4 ACO Chan 91

185° 005°

AKRON-CANTON RGNL (CAK)
ILS or LOC RWY 23