

ILS or LOC RWY 18R
CINCINNATI/NORTHERN KENTUCKY INTL (CVG)

MISSED APPROACH: Climb to 1300 then climbing right turn to 4000 on heading 270° and FLM VOR/DME R-314 to JADRO/FLM 43.3 DME/RADAR and hold.




	60	90	120	150	180
Knots	60	90	120	150	180
Min:Sec	5:00	3:20	2:30	2:00	1:40