

|  |                        |                             |   |
|--|------------------------|-----------------------------|---|
| WAAS<br>CH <b>42632</b><br><b>W35A</b> | APP CRS<br><b>352°</b> | Rwy Idg<br>TDZE<br>Apt Elev | <b>4809</b><br><b>3641</b><br><b>3649</b> |
|--|------------------------|-----------------------------|---|

RNAV (GPS) RWY 35

TRADEWIND (TDW)

RNP APCH-GPS.

NA

Procedure NA at night. Rwy 35 helicopter visibility reduction below 1 SM NA. Baro-VNAV NA. Use Rick Husband Amarillo Intl altimeter setting; when not received, use Hereford altimeter setting; increase LPV DA to 3983 feet, LNAV/VNAV DA to 4108 feet, and all MDAs 80 feet, and increase LNAV/VNAV all Cats and Circling Cat B visibility ¼ SM.

MISSED APPROACH: Climb to 4100 then climbing left turn to 6100 direct ZERAR and hold, continue climb-in-hold to 6100.

|                           |                                 |   |                          |                                 |
|---------------------------|---------------------------------|---|--------------------------|---------------------------------|
| AWOS-AV<br><b>118.475</b> | AMA ASOS<br><b>118.85 350.3</b> | AMARILLO APP CON★<br><b>119.5 307.0</b> | CLNC DEL<br><b>125.4</b> | UNICOM<br><b>122.8 (CTAF) 0</b> |
|---------------------------|---------------------------------|---|--------------------------|---------------------------------|

