

ILS or LOC RWY 36R  
HUNTSVILLE INTL-CARL T JONES FLD (HSV)

**MISSED APPROACH:** Climb to 4000 on heading 005° to intercept RQZ R-234 and right turn to RQZ VORTAC and hold, continue climb-in-hold to 4000. (TACAN aircraft continue climb to 5000 on RQZ VORTAC R-010 to VOYUD/RQZ 6.8 DME and hold north, left turn, 190° inbound, continue climb-in-hold to 5000).

[illegible]