

LOC RWY 17
ST MARY'S (KSM)(PASM)

MISSED APPROACH: Climb to 800 then climbing right turn to 2600 on heading 025° and on I-SMA north course to SAWNY/I-SMA 6.2 DME and hold, continue climb-in-hold to 2600.

CTAF
122.30