

WAAS CH 45635 W33A	APP CRS 330°	Rwy Ldg TDZE 7926 Apt Elev 7950
--	------------------------	---

RNAV (GPS) RWY 33

CENTRAL COLORADO RGNL (A.E.J)

NA

-21°C

Circling NA northeast of Rwy 15-33. DME/DME RNP-0.3 NA.
When local altimeter setting not received, use Salida altimeter setting
and increase all MDA 100 feet. VDP NA with Salida altimeter setting.
#Missed approach requires minimum climb of 425 feet per NM to 14100.

MISSED APPROACH: Climbing right
turn to 16000 direct KANON and hold,
continue climb-in-hold to 16000.

AWOS-3 132.925	DENVER CENTER 119.85 363.15	UNICOM 122.8 (CTAF) 0
--------------------------	---------------------------------------	---------------------------------

Procedure NA for arrivals at KANON on V244 eastbound.

MISSED APCH FIX

KANON

AKNAC

BUBYO

FIKEX

ROBKY

MSA ROBKY 25 NM

ELEV 7950 TDZE 7926

16000 KANON		VGSi and descent angles not coincident (VGSi Angle 3.00/TCH 41).		BUBYO	
*LNAV only.		*1.8 NM to ROBKY		12600	
ROBKY		330°		10300	
1.3		1.8 NM		3.4 NM	
7.7 NM		TCH 41			
CATEGORY		A	B	C	D
#LP	MDA	8960-1½	1034 (1100-1½)	8960-3 1034 (1100-3)	NA
LP	MDA	9840-1½	1914 (1900-1½)	9840-3 1914 (1900-3)	NA
#LNAV	MDA	9300-1½	1374 (1400-1½)	9300-3 1374 (1400-3)	NA
LNAV	MDA	9980-1½	2054 (2100-1½)	9980-3 2054 (2100-3)	NA
CIRCLING		9980-1½	2030 (2100-1½)	9980-3 2030 (2100-3)	NA

BUENA VISTA, COLORADO

Orig-B 31MAR16

38°49'N-106°07'W

CENTRAL COLORADO RGNL (A.E.J)

RNAV (GPS) RWY 33