

TACAN NBS  
Chan 73

APCH CRS  
345°

Rwy Idg  
TDZE  
Arpt Elev

6002  
21  
23

[USN]

BARKING SANDS PMRF (PHBK)

\*Circling not authorized E of Rwy 16-34.

MISSED APPROACH: Climbing left turn to 3000 on heading 177° and NBS TACAN R-222 to DIKNY and hold.

ATIS★  
128.0

HCF APP  
126.5 269.4

TOWER★  
126.2 360.2

GND CON★  
124.2 340.2

UNICOM  
122.8

BARKING SANDS  
Chan 73 NBS

R3101

2021  
182

4000

2000

564

16,000  
20°  
(211)

ASAYA  
NBS 12

GOMAW  
NBS 6

DIKNY  
NBS 15

1270°

HOLD 8000  
3000

042°

230K

222°

NBS 20

R-222

165°

HOLD 18,000  
16,000

345°

R-165

NBS 37

\*\* Or as assigned

16,000

(IAF) HOSAX  
NBS 25

Use of SOK feeder  
requires turn in hold

SOUTH KAUAI  
115.4 SOK  
Chan 101

(b) 160

(a) 275

(c) 095

(c)

MSA NBS 2.5 NM

155°

7500

4300

355°

EMERG SAFE ALT 100 NM 7500

3000

NBS R-222

DIKNY NBS 15

NBS TACAN

MAPIE NBS 1.9

NBS 2.6

GOMAW NBS 6

ASAYA NBS 12

HOSAX R-165 NBS 25

16,000

\*\* Or as assigned

3000

345°

2.94°

TCH 40

0.5 NM

4.1 NM

1500

CATEGORY	C	D	E
S-34	460-1¼	439 (500-1¼)	
CIRCLING*	480-1½ 457 (500-1½)	580-2	557 (600-2)

ELEV 23

TDZE 21

30

91

34

345°

HIRL Rwy 16-34

TWR

83

KEKAHA, KAUAI I, HAWAII

22°01'N-159°47'W

BARKING SANDS PMRF (PHBK)

Amtd 7 12JUN25

HI-TACAN Z RWY 34