

**TERRACE** BC (CYXT) 3 S UTC-8(-7DT) N54°28.11' W128°34.70' H-10, L-1D  
 713 B NOTAM FILE CYXT Not insp.

**RWY 15-33:** H4797X148 (ASPH) HIRL  
**RWY 15:** ODALS. REIL. PAPI(P2R)—GA 3.5°. RVR  
**RWY 33:** SSALR. REIL. PAPI(P2L)—GA 3.5°. Rgt tfc. RVR

**RWY 03-21:** H5371X148 (ASPH)

**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 03:** TORA-5371 TODA-6355 ASDA-5371 LDA-5371  
**RWY 15:** TORA-7497 TODA-8481 ASDA-7497 LDA-7497  
**RWY 21:** TORA-5371 TODA-6355 ASDA-5371 LDA-5371  
**RWY 33:** TORA-7497 TODA-8481 ASDA-7497 LDA-7497

**SERVICE: FUEL** 100LL, JET A1, FS-II **LGT** PAPI limitation/restriction. PAPI Rwy 33 to be used only within 2 NM of thld. Hi terrain reduces operational length of Rwy 33 PAPI.

**AIRPORT REMARKS:** Attended 13-08Z (DT 12-07Z). Gliders opr off rwy to SW of arpt by NOTAM. Ngt ops not recommended unless all hazard bcns are opr. Recommend that only pilots familiar with the lcl area use the arpt during hrs of darkness. Twy A and B AGN IIB. Twy B unctld first 2000' from apron. Fuel avbl 1230-0400Z (DT1130-0300Z) ctc 250-638-1564, OT call out charge. ARFF services: Participating CAT 5 1745-0325Z (DT 1645-0225Z) for sked pax fit, other acft 2 hr PN 250-615-7636. Call out chg. Designated CAT 6 1330-0740Z (DT1230-0640Z) for scheduled commercial. Tran acft must park in SE corner of Apron. Itinerant parking with tiedowns on grass May to Oct. N side main apron stands 1-3 are rstd to sked tfc only. Itinerant pilot/pax access via pilot access door on E end of tml bldg. No access/egress via tml bldg facility is permitted. Exceptions require prior approval of arpt opr. Corporate itinerant prkg available. Win maint 16-04Z (DT 15-03Z). No win maint Rwy 03-21. Ltd hrs CRFI, PLR/PCN. Rwy 03 slope 0.69% up. All stands PPR.

**COMMUNICATIONS:**  
**RADIO** 122.0 (E) PTC avbl.  
**RCO** 123.375 (PACIFIC RADIO)  
**VANCOUVER CENTER APP/DEP CON** 128.4 269.1  
**VFR ADVISORY SVC** call Terrace Radio on Mandatory Frequency (MF) 3700 MSL within 5 NM.

**RADIO AIDS TO NAVIGATION**  
**NDB(MHW)** 332 XT N54°22.44' W128°35.07' 343° 5.7 NM to fld./19E.  
**KITIMAT NDB(HZ)** 203 ZKI N54°03.25' W128°40.21' 348° 25.1 NM to fld./19E.  
**ILS/DME** 110.1 I-IXT Chan 38 Rwy 33. Localizer reliable only within 10° either side of centerline.

**COMM/NAV/WEATHER REMARKS:** Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA). METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.

**TESLIN** YT (CYZW) 0 NW YUKON GOV'T UTC-8(-7DT) N60°10.37' W132°44.64' WHITEHORSE  
H-1C  
 2303 B AOE NOTAM FILE CYZW Not insp.

**RWY 09-27:** 5028X100 (GRVL) HIRL  
**RWY 09:** REIL. PAPI(P2L)—GA 3.0°. Rgt tfc.  
**RWY 27:** REIL. PAPI(P2L)—GA 4.0°.

**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 09:** TORA-5028 TODA-5193 ASDA-5028 LDA-5028  
**RWY 27:** TORA-5028 TODA-5193 ASDA-5028 LDA-5028

**SERVICE: LGT** ACTIVATE LIRL Rwy 09-27 and rot bcn—122.1. PAPI may require 3-5 min to activate via ARCAL in cold temperatures.

**AIRPORT REMARKS:** Ltd winter maintenance. Rwy sfc soft in spring and when wet. Fuel storage by permit only ctc opr. Rwy 27 slope down 0.50%. Compacted snow/grvl mix during winter conds. Sfc may be soft during freeze and thaw periods.

**COMMUNICATIONS:**  
**RADIO** 122.1 (V) (1300-0100Z‡ Jun 1-Sep 30; 1600-0000Z‡ Oct 1-May 31)

**COMM/NAV/WEATHER REMARKS:** Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA). CARS: 867-390-2525 ltd hrs. METAR dur CARS hrs OT LWIS. TAF 1800-0000Z‡ Oct 1-May 31; 1500-0100Z‡ Jun 1-Sep 30; issue times: 1800Z‡ Oct 1-May 31; 1500Z‡, 1800Z‡ Jun 1-Sep 30.