

**ANN ARBOR MUNI** (ARB)(KARB) 3 S UTC-5(-4DT) N42°13.38' W83°44.74'

839 B NOTAM FILE ARB

**RWY 06-24:** H3505X75 (CONC-GRVD) S-45, D-70 MIRL

**RWY 06:** REIL. PAPI(P4L)—GA 3.0° TCH 20'.

**RWY 24:** VASI(V2L)—GA 3.0° TCH 20'. Road.

**RWY 12-30:** 2750X110 (TURF) 0.6% up NW

**RWY 12:** Tree.

**RWY 30:** Tree.

**SERVICE:** S4 FUEL 100LL, JET A+ OX 1, 2, 3, 4 LGT When twr clsd ACTIVATE REIL Rwy 06, PAPI Rwy 06, VASI Rwy 24, MIRL Rwy 06-24—CTAF.

**AIRPORT REMARKS:** Attended Apr-Oct 1300-0100Z†, Nov-Mar 1300-2300Z†. Trml open 1200Z†-dusk. Deer and birds on and in/ov arpt. When twr clsd, confirm snow removal ops and winter conditions—CTAF. Rwy 12-30 no snow removal. Rwy 24 runup area, first 200' of Twy A, Twy A1 between Twy A and Rwy 24 hold line not vsb fm twr. Rwy 12-30 marked with 3' yellow cones.

**AIRPORT MANAGER:** 734-994-9124

**WEATHER DATA SOURCES:** ASOS (734) 668-7173 LAWRS.

**COMMUNICATIONS:** CTAF 120.3 ATIS 134.55 UNICOM 123.0

Ⓡ **DETROIT APP/DEP CON** 118.95

**TOWER** 120.3 (1300-0100Z†) **GND CON** 121.6 **CLNC**

**DEL** 121.6

**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc Detroit Apmh at 734-955-1404.

**AIRSPACE:** CLASS D svc 1300-0100Z†; other times CLASS G.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAN.

**SALEM (L) VORTACW** 114.3 SVM Chan 90 N42°24.52' W83°35.63' 214° 13.0 NM to fld. 956/3W.

TACAN AZIMUTH unusable:

215°-255° byd 10 NM

VOR unusable:


094°-121° byd 10 NM blo 5,000'

094°-121° byd 20 NM blo 8,000'

DME unusable:

099°-115° byd 15 NM blo 5,000'

099°-115° byd 20 NM blo 8,000'



**DETROIT  
COPTER  
L-28J, A  
IAP, AD**

**ANTRIM CO** (See BELLAIRE on page 160)

**ARNOLD FLD** (See CROSWELL on page 174)

**ATLANTA MUNI** (Y93) 1 SE UTC-5(-4DT) N44°59.81' W84°07.63'

880 NOTAM FILE LAN

**RWY 13-31:** 3223X100 (TURF) LIRL

**RWY 13:** Thld dspclcd 758'. Trees.

**RWY 31:** Thld dspclcd 569'. Trees.

**RWY 05-23:** H3000X60 (ASPH) LIRL 0.3% up SW

**RWY 05:** Thld dspclcd 1494'. Trees.

**RWY 23:** PAPI(P2L)—GA 4.0° TCH 22'. Thld dspclcd 370'. Road.

**SERVICE:** LGT ACTIVATE PAPI Rwy 23; LIRL Rwy 05-23 and Rwy 13-31—CTAF. Rwy 13-31 LIRL ops Jun-Sep.

**AIRPORT REMARKS:** Attended on call. Deer and lg birds on and in/ov arpt. Rwy 13-31 CLOSED Nov-Apr and when snow covd.

No snow removal. For svc call amgr. Rwy 05-23 cfm winter conds and snow removal prior to use—call amgr or asst amgr.

Rwy 13-31 marked with 3' yellow cones. Rwy 05-23 runway markings faded.

**AIRPORT MANAGER:** 989-306-6408

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE APN.

**ALPENA (L) VORTAC** 108.8 APN Chan 25 N45°04.97' W83°33.42' 265° 24.8 NM to fld. 678/7W.

TACAN AZIMUTH unusable:

260°-280° byd 30 NM blo 4,000'

DME portion unusable:

260°-280° byd 30 NM blo 4,000'

**AU SABLE** N44°26.95' W83°23.66' NOTAM FILE OSC.

(DH) DME 116.1 ASP Chan 108 at Oscoda/Wurtsmith. 625.

DME unusable:

293°-013° byd 35 NM blo 3,000'

**LAKE HURON  
L-31C**

**LAKE HURON  
H-11A, L-31C**