

CARMEL N41°16.81' W73°34.88' NOTAM FILE ISP.
(L) (L) **VOR/DME** 116.6 CMK Chan 113 051° 7.1 NM to Danbury Muni. 693/12W.

VOR unusable:

001°-155°

195°-225°

245°-270°

325°-355°

DME unusable:

000°-015° byd 20 NM

034°-054° byd 20 NM

055°-135° byd 20 NM blo 5,000'

180°-200°

340°-359° byd 20 NM blo 6,000'

NEW YORK
COPTER
H-101, L-33B, 34I

CATTARAUGUS CO—OLEAN (See OLEAN on page 235)

CHAPIN FLD (See CAMBRIDGE on page 194)

CHAUTAUQUA CO/DUNKIRK (See DUNKIRK on page 198)

CHAUTAUQUA CO/JAMESTOWN (See JAMESTOWN on page 213)

CLARENCE AERODROME (See BUFFALO on page 193)

CLAY

AIRLINE ENTERPRISES (1H1) 1 N UTC-5(-4DT) N43°12.35' W76°10.76'

NEW YORK

385 NOTAM FILE BUF

RWY 01-19: 2220X75 (TURF)

RWY 01: Brush.

RWY 19: Trees.

RWY 10-28: 1550X97 (TURF)

RWY 10: Trees.

RWY 28: Trees.

AIRPORT REMARKS: Attended dalgt hrs. Deer on and invof arpt. Fld soft late fall and early spring. Ski ops in winters. Paraplane activity, evenings and weekends. Rwy 10 line of trees +95' high, 55' left. Rwy 01-19 width varies 75' to 90'. Rwy 10-28 width varies 97' to 136'. Rwy 10-28 edges marked with barrels. Rwy 01-19 edges marked with barrels. 100' long parl ditch rt edge of Rwy 01 first 300'. Rwy 01 20' ver drop 100 to 400' f rwy end.

AIRPORT MANAGER: 315-699-5734

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.

COLUMBIA CO (See HUDSON on page 211)

COOPERSTOWN—WESTVILLE (K23) 4 SE UTC-5(-4DT) N42°37.75' W74°53.46'

NEW YORK

1260 NOTAM FILE BUF

RWY 02-20: 2337X125 (TURF) MIRL(NSTD)

RWY 02: NSTD. Trees. Rgt tfc.

RWY 20: NSTD. Crops.

SERVICE: S4 **FUEL** 100LL **LGT** ACTIVATE MIRL Rwy 02-20—CTAF. Rwy 02-20 NSTD MIRL spacing, 2 thld lgts each side.

AIRPORT REMARKS: Unattended. 87 octane also avbl. Self svc fueling avbl. Call manager for svcs. Rwy edge mkd by yellow tires arnd edge lgts.

AIRPORT MANAGER: 607-437-8308

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.