

| | | | | | |
|---|--|--------------------------------|-------------------------------------|---|--|
| Flight Procedures Cover Page | Task Action: P-NOTAM | Task Type: IAP | Estimated Chart Date: 12/31/2020 | APWS Task ID: 0C135829116D4B2CBB0AF0449EA6E918 | APWS Project ID: DDD55C1A5CE241358F318C4D7B46543F |
| Procedure: RNAV (GPS) RWY 12 AMDT 0A | | Enroute: NO | Specialist: Gotcher, Austin | | Agreement Number: |
| Airport ID: KTAN | Airport Name: TAUNTON MUNI - KING FIELD | Airport City: TAUNTON | | | State: MA |
| Facility ID: | Facility Type: | Flight Inspection Remark Type: | | | |
| <div>Procedure Comments: P-NOTAM PROJECT TO INCORPORATE NOTAM 0/1354. "PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJF-10) MEMO, APRIL 29, 2020 SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED." CONTACT: JOHN BORDY 405-954-0980; AJV-A422 POC.</div> | | | | | |

QUALITY
9
CHECKED