

[Print](#)

Project Name: HBG, MS, LNAV/VNAV Missed Approach Obstacle

Project Reason: RNAV(GPS) Y RWY 13: CAT D Missed Sec 2: 397 TOWER (28-020480) 311508.81N/0891632.28W (1A)
RNAV(GPS) Z RWY 13: CAT B, C, D Missed Sec 1: 334 TOWER (28-059729) 311606.70N/0891641.30W (1A), CAT D
Missed Sec 2: 397 TOWER (28-020480) 311508.81N/0891632.28W (1A). UPDATE NOTES ON BOTH APPROACHES.

Last Updated By: Timothy Johnson

Last Updated At: 2025-04-16 17:03:57.057168

Status: Verified

!FDC 5/4579 HBG IAP HATTIESBURG BOBBY L CHAIN MUNI, HATTIESBURG, MS. RNAV (GPS) Z RWY 13, AMDT 1C...
LNAV/VNAV DA 536/HAT 385 ALL CATS, VIS 1 1/8 ALL CATS. CHANGE PBN EQUIPMENT REQUIREMENTS NOTE TO
READ: RNP APCH - GPS. DELETE PROFILE NOTE: *LNAV ONLY. DELETE ASTERISK FROM MINIMUM ALTITUDE AT
NETTI/2.80 NM TO RW13 1080. DELETE ASTERISK FROM VDP AT 1.19 NM TO RW13. THIS IS RNAV (GPS) Z RWY 13,
AMDT 1D. 2504161703-PERM

QUALITY
32
CHECKED

Digitally signed by

CASEY D HILL

May 23, 2025