

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 12/26/2024	APWS Task ID: 14169AF0114A4C96BCBF48A8B4A94B81	APWS Project ID: 00344DF84BF242D185A7DA49CF77F603
Procedure: RNAV (GPS)-A AMDT 0B		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: KHWV			Airport City: SHIRLEY		State: NY
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: ACTIVE DATA USED.</div> <div>CLEARs T-NOTAM 3/2602.</div> <div>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.</div> <div>CONTACT: DAVID DANNER (405)-954-5077.</div> <div><div>QUALITY 41 CHECKED</div><div>QUALITY 34 CHECKED</div></div>					

APP CRS  
239°

Rwy Idg  
TDZE  
Apt Elev  
81

N/A  
N/A  
81

RNAV (GPS)-A  
BROOKHAVEN (HWV)

RNP APCH - GPS.

▼  
▲

When local altimeter setting not received, use Long Island MacArthur altimeter setting and increase all MDAs 40 feet. Rwy 15 and 33 helicopter visibility reduction below 1 SM NA. Circling Rwy 15, 33 NA at night.

MISSED APPROACH: Climb to 2000 direct PIRCE and hold.

ASOS 119.625	NEW YORK APP CON 120.05 343.75	CLNC DEL 133.2	UNICOM 122.8 (CTAF) 0
-----------------	-----------------------------------	-------------------	--------------------------

