

[Print](#)

Project Name: KEWR - RNAV (GPS) RWY 11 ADD NOT COINCIDENT NOTE

Project Reason: NEWARK LIBERTY INTL (KEWR) NEWARK, NJ - PER 28-DAY REVIEW, PENDING DATA FOR 12/2/2021, KEWR RWY 11 VGSI ANGLE/TCH CHANGED FROM 3.08/57.6 TO 3.00/60.4. THE NEW FLIGHT INSPECTION COMMISSIONED PAPI SURVEYED DATA VALUE IS NOT COINCIDENT WITHIN 3 FEET TOLERANCE IAW FAAO 8260.19I, PARA 8-6-9.M. CHANGED PBN REQUIREMENTS NOTE TO READ RNP APCH - GPS - ADDED GPS PER FAAO 8260.19I, PARA 8-6-8. CHANGED HELICOPTER NOTE FROM VISIBILITY REDUCTION BY HELICOPTERS NA TO RWY 11 HELICOPTER VISIBILITY REDUCTION BELOW RVR 4000 NOT AUTHORIZED - 34:1 PENETRATIONS EXIST AND RVR EQUIPMENT IS INSTALLED PER FAAO 8260.19, PARA 8-6-11.

Last Updated By: William Hanby

Last Updated At: 2021-11-08 17:52:14.067638

Status: Verified **1/3868**

!IFDC ~~XXXX~~ EWR IAP NEWARK LIBERTY INTL, NEWARK, NJ. RNAV (GPS) RWY 11, ORIG-G... CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT (VGSI ANGLE {ANGLE}/TCH {FEET}). CHANGE PBN REQUIREMENTS NOTE TO READ: RNP APCH - GPS. CHANGE HELICOPTER VISIBILITY NOTE TO READ: RWY 11 HELICOPTER VISIBILITY REDUCTION BELOW RVR 4000 NOT AUTHORIZED. THIS IS RNAV (GPS) RWY 11, ORIG H. 2111081752-PERM



Digitally signed by
CASIMIR L TABAKA
Dec 01, 2021