

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 12/01/2022	APWS Task ID: 199EF7018C2E4A929970CE1661AEB161	APWS Project ID: 2214930D30854B72B8D149A8AF715B31
Procedure: VOR OR TACAN RWY 10 AMDT 2C		Enroute: NO	Specialist: Combs, Patrick		Agreement Number:
Airport ID: TJSJ			Airport City: SAN JUAN		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments: ACTIVE AIRPORT AND RWY DATA USED.</p> <p>CANCELS NOTAM FDC 2/4110.</p> <p>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.</p> <p>CONTACT JASON KRETSCHMER, AJV-A421, 405-954-4019.</p> <p style="text-align: center;"><i>Digitally signed by</i> JASON KRETSCHMER Oct 17, 2022</p>					

