


<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 04/25/2018	<b>Task #:</b> 2014011226989901005	<b>Request #:</b> 20140112269899
<b>Procedure:</b> RNAV (GPS) RWY 36 AMDT 1B			<b>Airport ID:</b> KPSN	<b>Airport:</b> PALESTINE MUNI		<b>Reimbursable #:</b> NO
<b>City:</b> PALESTINE	<b>ST:</b> TX	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 01/03/2019		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>		<b>Specialist:</b> KELLY DEAN		
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	02/03/2015			<div style="text-align: center;">  </div>		
<b>QA:</b>						
<b>Liaison:</b>						
<b>Procedure Comments:</b>			<b>Remark Type:</b> INFORMATION			
P-NOTAM FDC 8/2363  POC FOR THIS ACTION IS DON LANIER 405-954-8242  FLIGHT INSPECTION REVIEW NOT REQUIRED - PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, DEC 22, 2017.						

APP CRS	Rwy Idg	5005
357°	TDZE	415
	Apt Elev	423

RNAV (GPS) RWY 36  
PALESTINE MUNI (PSN)

<p>▼ VDP NA with C. David Campbell Field-Corsicana Muni altimeter setting. ▲ DME/DME RNP-0.3 NA. If local altimeter setting not received, use C. David Campbell Field-Corsicana Muni altimeter setting and increase all MDAs 100 feet.</p>	<p>MISSED APPROACH: Climb to 2500 direct CERBU WP and hold.</p>
--	---

AWOS-3 118.025	FORT WORTH CENTER 135.25 265.1	UNICOM 122.7 (CTAF) 1
-------------------	-----------------------------------	--------------------------

