


| | | | | | | |
|--|---------------|--------------------------------|---|--|---------------------------------------|-------------------------------------|
| Flight Procedure Tracking Form | | Action: FLIGHT CHECK | Task Type: TEXTUAL DP | Date Open: 12/07/2017 | Task #: 2014101734360902007 | Request #: 20141017343609 |
| Procedure: DEVELOPE TAKEOFF MINIMUMS FOR NEW AIRPORT | | | Airport ID: K4V0 | Airport: RANGELY | | Reimbursable #: NO |
| City: RANGELY | ST: CO | GPS #: | Estimated Chart Date: 05/24/2018 | | FICO #: | |
| Fac ID: N/A | | Fac. Type: | | | Specialist: FRANK MOORE | |
| Procedure Review | | | | | | |
| | Rec'd | Rel'd | Full Name | Comments | | |
| Lead: | 08/31/2017 | 12/12/2017 | DAVID TEFFETELLER |  <i>Digitally signed by</i> DAVID W SAUER Feb 21, 2018 | | |
| QA: | 12/12/2017 | | | | | |
| Liaison: | | | | | | |
| Procedure Comments: | | | ENROUTE-NON Remark Type: INFORMATION | | | |
| CONTACT DAVID TEFFETELLER 301-471-4767 | | | | | | |