

<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> IAP	<b>Date Open:</b> 08/03/2017	<b>Task #:</b> 201707273383870H001	<b>Request #:</b> 20170727338387
<b>Procedure:</b> RNAV (GPS) RWY 4 AMDT 1A			<b>Airport ID:</b> KFOM	<b>Airport:</b> FILLMORE MUNI		<b>Reimbursable #:</b> NO
<b>City:</b> FILLMORE	<b>ST:</b> UT	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 02/01/2018		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>			<b>Specialist:</b> JAMES LAFFERTY	
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	08/04/2017	10/13/2017	TRACEY STILES	QUALITY - Digitally signed by		
<b>QA:</b>	10/12/2017			24 DAVID W SAUER		
<b>Liaison:</b>				CHECKED Dec 19, 2017		
<b>Procedure Comments:</b> ENROUTE-NON <b>Remark Type:</b> INFORMATION  12/19/17: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 10/13/17 1. CHANGE TERMINAL ROUTE RW04 (MAP) COURSE FROM "014.43" TO "041.43".  "PROCESSED IAW FLIGHT INSPECTION TEAM (AJW-333) MEMO, MAY 30, 2017, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED". CONTACT DAVE TEFFETELLER 301-427-4767 OR PATRICK MULQUEEN 405-954-4073						