


Flight Procedure Tracking Form		Action: AMENDMENT	Task Type: IAP	Date Open: 11/05/2017	Task #: 2017110536408901001	Request #: 20171105364089
Procedure: APPROACH ILS OR LOC RWY 30 R AMDT 31A			Airport ID: KBFL	Airport: MEADOWS FIELD		Reimbursable #: NO
City: BAKERSFIELD	ST: CA	GPS #:	Estimated Chart Date: 05/24/2018		FICO #:	
Fac ID: N/A		Fac. Type:		Specialist: ROBERT COOK		
Procedure Review						
	Rec'd	Rel'd	Full Name	Comments		
Lead:	11/06/2017					
QA:						
Liaison:						
Procedure Comments: P NOTAM 8/2899 ENROUTE-NON Remark Type: INFORMATION PROCESSED IAW FLIGHT INSPECTION TEAM (AJW-333) MEMO, 30 MAY, 2017 SUBJECT: FLIGHT INSPECTION NOT REQUIRED. DELETED CHART PROFILE NOTE: VGSI AND ILS GLIDEPATH NOT COINCIDENT (VGSI ANGLE {ANGLE}/TCH {FEET}).-VGSI COMMISSIONED/COINCIDENTAL WITH ILS GLIDESLOPE. IN BOTH INOPERATIVE NOTES, CHANGED THE ACRONYM MALSR TO ALS.-CRITERIA. PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-333) MEMO, DEC 22, 2017, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED. CONTACT ALLAN WILL, AJV-5412, 405-954-6103, ALLAN.WILL@FAA.GOV						