

Flight Procedure Tracking Form		Action: FLIGHT CHECK	Task Type: IAP	Date Open: 12/07/2017	Task #: 2017120732486301001	Request #: 20171207324863
Procedure: RNAV (GPS) RWY 35 AMDT 1A			Airport ID: KTQH	Airport: TAHLEQUAH MUNI		Reimbursable #: NO
City: TAHLEQUAH	ST: OK	GPS #:	Estimated Chart Date: 09/13/2018		FICO #: 1212032	
Fac ID: N/A		Fac. Type:		Specialist: CHARLES THIBODEAUX		
Procedure Review						
	Rec'd	Rel'd	Full Name	Comments		
Lead:	01/24/2018	07/27/2018	DAVID DANNER	QUALITY		
QA:	07/16/2018	05/18/2018	DAVID DANNER	4 8/8CTabaka		
Liaison:	05/18/2018	05/21/2018	MARY MCDONALD	CHECKED		
Procedure Comments:			ENROUTE-NON			
			Remark Type: INFORMATION			
<p>7/13//2018: THIS IS AN CORRECTED COPY OF THE FORM APPROVED ON 06/25/2018:</p> <p>1. CHANGED CA LEG COURSE FROM 002.23 TO 357.23.</p> <p>ABBREVIATED AMENDMENT.</p> <p>RAISED TAA ALTITUDE STRAIGHT-IN SEGMENT 267/30 CW 087/30 TO 267/10 CW 087/10 FROM 3400 TO 3700.</p> <p>ESTABLISHED VDP AT 1.6NM FROM RUNWAY 35 - 20:1 SURFACE IS CLEAR.</p> <p>CONTACT LONNIE EVERHART: 405.954.4576</p> <p>8/8/2018: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 07/17/2018:</p> <p>1. CHANGED CA LEG FROM "FO" TO "FB".</p>						