

TRANSMITTAL OF AIRWAYS/ROUTES DATA

AIRWAY NO or ROUTE

Q75

ROUTINE or DOCKET NO

18-ASO-5

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
ENEME	GA	FB	TEUFL	GA	FB	2.0	TF
<u>OBSTRUCTION</u>	<u>COORDINATES</u>		<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
18000			45000						18000

<u>COP</u>		<u>FIX MRA</u>		<u>FIX MCA</u>		<u>MTA</u>
------------	--	----------------	--	----------------	--	------------

SEGMENT REMARKS

AMG, CRG, OTK, SAV

CHANGES-REASON

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
TEUFL	GA	FB	TEEEM	GA	FB	2.0	TF
<u>OBSTRUCTION</u>	<u>COORDINATES</u>		<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
18000			45000						18000

<u>COP</u>		<u>FIX MRA</u>		<u>FIX MCA</u>		<u>MTA</u>
------------	--	----------------	--	----------------	--	------------

SEGMENT REMARKS

AMG, CRG, IRQ, MCN, SAV, OTK

CHANGES-REASONQUALITY
41
CHECKED

TRANSMITTAL OF AIRWAYS/ROUTES DATA

AIRWAY NO or ROUTE

Q75

ROUTINE or DOCKET NO

18-ASO-5

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
TEEEM	GA	FB	SHRIL	GA	FB	2.0	TF

<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>
--------------------	--------------------	-----------------	-----------------	-----------	------------	--------------------

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
18000			45000						18000

<u>COP</u>	<u>FIX MRA</u>	<u>FIX MCA</u>	<u>MTA</u>
------------	----------------	----------------	------------

SEGMENT REMARKS

AMG, CAE, CHS, GRD, IRQ, MCN, SAV

CHANGES-REASON

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
SHRIL	GA	FB	FISHO	SC	FB	2.0	TF

<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>
--------------------	--------------------	-----------------	-----------------	-----------	------------	--------------------

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
18000			45000						18000

<u>COP</u>	<u>FIX MRA</u>	<u>FIX MCA</u>	<u>MTA</u>
------------	----------------	----------------	------------

SEGMENT REMARKS

CAE, CHS, GRD, IRQ, SAV, AMG

CHANGES-REASON

QUALITY
41
CHECKED

TRANSMITTAL OF AIRWAYS/ROUTES DATA

AIRWAY NO or ROUTE

Q75

ROUTINE or DOCKET NO

18-ASO-5

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
FISHO	SC	FB	ILBEE	SC	FB	2.0	TF
<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>	

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
18000			45000						18000
<u>COP</u>				<u>FIX MRA</u>		<u>FIX MCA</u>			<u>MTA</u>

SEGMENT REMARKS

CAE, CHS, FLO, GRD, IRQ, SAV, SPA

CHANGES-REASON

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
ILBEE	SC	FB	SLOJO	SC	FB	2.0	TF
<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>	

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
18000			45000						18000
<u>COP</u>				<u>FIX MRA</u>		<u>FIX MCA</u>			<u>MTA</u>

SEGMENT REMARKS

CAE, FLO, GRD, GSO, IRQ, SPA

CHANGES-REASON

QUALITY
41
CHECKED

TRANSMITTAL OF AIRWAYS/ROUTES DATA

AIRWAY NO or ROUTE

Q75

ROUTINE or DOCKET NO

18-ASO-5

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
SLOJO	SC	FB	GREENSBORO (GSO) VORTAC	NC	FB	2.0	TF
<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>	

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
18000			45000						18000
<u>COP</u>				<u>FIX MRA</u>		<u>FIX MCA</u>			<u>MTA</u>

SEGMENT REMARKS

CAE, FLO, GRD, GSO, IRQ, PSK, RDU, SPA

CHANGES-REASON

<u>FLIGHT CHECK</u>	<u>DATE</u>	<u>OFFICE</u>	<u>NAME</u>
FLIGHT INSPECTION REVIEW NOT REQUIRED - PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-333) MEMO, DEC 22, 2017.			

<u>APPROVED</u>	<u>DATE</u>	<u>OFFICE</u>	<u>TITLE</u>	<u>NAME</u>
<i>Digitally signed by</i> JULIE A MORGAN	Aug 15, 2018			
<i>Digitally signed by</i> JULIE A MORGAN	Aug 15, 2018	AJV-5400	MANAGER	LONNIE EVERHART

