


Flight Procedure Tracking Form		Action: AMENDMENT	Task Type: SID	Date Open: 07/05/2018	Task #: 2018061827549501004	Request #: 20180618275495
Procedure: SID HOODO (RNAV) SIX BAYTOWN TX K54T			Airport ID: K54T	Airport: RWJ AIRPARK		Reimbursable #: NO
City: BAYTOWN	ST: TX	GPS #:	Estimated Chart Date: 04/25/2019		FICO #:	
Fac ID: N/A		Fac. Type:		Specialist: ROBERT GRIM		
Procedure Review						
	Rec'd	Rel'd	Full Name	Comments		
Lead:	07/10/2018			 <i>Digitally signed by</i>		
QA:				DONALD H LANIER		
Liaison:				Feb 15, 2019		
Procedure Comments: ENROUTE Remark Type: INFORMATION						
<p>PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.</p> <p>THIS CANCELS FDC NOTAM: 8/9692</p> <p>CONTACT INFO: DON LANIER AJV-5431 MANAGER, 405.954.8242</p> <p>02/15/19: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 12/10/18.</p> <p>1. ADDED RWY 22 TO TAKEOFF MINIMUMS FOR ELLINGTON (KEFD). RWY 4, 17L, 17R, 22, 35L, 35R STANDARD WITH MINIMUM CLIMB OF 500 FT PER NM TO 540.</p>						