


<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> FIX	<b>Date Open:</b> 08/28/2018	<b>Task #:</b> 2018082831575501001	<b>Request #:</b> 20180828315755
<b>Procedure:</b> FIX PALM SPRINGS VORTAC 19 CA US			<b>Airport ID:</b> CA	<b>Airport:</b>		<b>Reimbursable #:</b> NO
<b>City:</b>	<b>ST:</b> CA	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 06/20/2019		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>		<b>Specialist:</b> TYLER MITCHELL		
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	08/28/2018	02/08/2019	DAVID FRESELLA			
<b>QA:</b>	02/08/2019					
<b>Liaison:</b>						
<b>Procedure Comments:</b>			ENROUTE-NON	<b>Remark Type:</b> INFORMATION		
<p>FIX ONLY PROJECT TO AMEND HOLDING ALTITUDE.</p> <p>CONTACT ROBERT HAMILTON 405-954-4608</p>						