

<b>Flight Procedure Tracking Form</b>		<b>Action:</b> AMENDMENT	<b>Task Type:</b> FIX	<b>Date Open:</b> 11/26/2018	<b>Task #:</b> 2018112632701101001	<b>Request #:</b> 20181126327011
<b>Procedure:</b> FIX ROKEE 2 IL US			<b>Airport ID:</b> IL	<b>Airport:</b>		<b>Reimbursable #:</b> NO
<b>City:</b>	<b>ST:</b> IL	<b>GPS #:</b>	<b>Estimated Chart Date:</b> 01/03/2019		<b>FICO #:</b>	
<b>Fac ID:</b> N/A		<b>Fac. Type:</b>		<b>Specialist:</b> KISSY MAXFIELD		
<b>Procedure Review</b>						
	<b>Rec'd</b>	<b>Rel'd</b>	<b>Full Name</b>	<b>Comments</b>		
<b>Lead:</b>	11/26/2018			Digitally signed by		
<b>QA:</b>				BEV L BORDY		
<b>Liaison:</b>				Nov 27, 2018		
<b>Procedure Comments:</b>			<b>Remark Type:</b> INFORMATION			
<p>PROCESSED IAW FLIGHT INSPECTION TEAM (AJW-333) MEMO, MAY 30, 2017, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED CONTACT LONNIE EVERHART: 405.954.4576</p> <p>11/29/18: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 11/27/18. 1. KLUBS: ADDED SPECIAL IAP AND CONTROLLER LOW TO REQUIRED CHARTING. 2. ROKEE: CHANGED IAP TO SPECIAL IAP AND CONTROLLER LOW TO REQUIRED CHARTING.</p>						