

[Print](#)

Project Name: Chart Note Updates (KPCW)

Project Reason: During a Periodic Review, it was found that 34:1 penetrations existed to runway 9. Additionally, during a review of the circling portion of the procedure, it was found that 20:1 penetrations also existed for RWY's 18 and 36. Because of these penetrations, a helicopter note needs to be added to RWY 9, and a circling not authorized for RWY's 18/36 at night. The PBN Requirements note: RNP APCH needs to be added. Also, chart note DME/DME RNP-0.3 NA needs to be removed.

Last Updated By: James Lafferty

Last Updated At: 2019-10-28 16:52:05.5078

Status: Draft

9/8155

!FDC X/XXXX PCW IAP ERIE-OTTAWA INTL, PORT CLINTON, OH. RNAV (GPS) RWY 9, AMDT 1A... DELETE NOTE: DME/DME RNP-0.3 NA. CHART NOTE: RWY 9 HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. ADD PBN REQUIREMENTS NOTE: RNP APCH. CHART NOTE: CIRCLING RWY 18, 36 NA AT NIGHT. 34:1 IS NOT CLEAR. THIS IS RNAV (GPS) RWY 9, AMDT 1B. 1910281652-PERM

P-NOTAM DOES NOT
AFFECT CODING

QUALITY
26
CHECKED

QUALITY
24
CHECKED

Digitally signed by
DAVID TEFFETELLER
Nov 05, 2019