

<b>NAME:</b> PURME	<b>STATE:</b> NC	<b>COUNTRY:</b> US	<b>ICAO REGION CODE:</b> K7
<b>LATITUDE/LONGITUDE:</b> 354800.16N/0785237.10W	<b>TYPE:</b> WP, RADAR, DME		

FIX MAKE-UP FACILITIES:											
FAC	NAME	IDENT	TYPE	CLASS	MAG BRG	TRUE BRG	DME	DIST NM	FROM FAC FEET	MRA	MAA
1	RALEIGH/DURHAM	I-RDU	LOC/DME		234.14	225.14	6.87	6.89	41839	2200	4900

REMARKS:  
ILS DME COORDINATES: 355254.38N/0784641.19W

QUALITY  
18  
CHECKED