


Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 08/11/2022	APWS Task ID: 3471200059E94B2B90134C3AFF2F1940	APWS Project ID: 0260E37A78F64A9CAA57BCAEE799F39B
Procedure: RNAV (GPS) RWY 4, AMDT 1B		Enroute: NO	Specialist: Rogers, James		Agreement Number:
Airport ID: KESN			Airport City: EASTON		State: MD
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
<p>Procedure Comments: P-NOTAM CLEARS FDC 0/2974. LNAV/VNAV DA 625/HAT 567, LNAV/VNAV ALL CATS VISIBILITY 1 5/8 SM. UPDATED PROCEDURE NOTES.</p> <p>"PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION"</p> <p>POC: MARK ADAMS, AJV-A412 LEAD, 405.954.9946.</p> <p>2/8978</p>					

QUALITY
29
CHECKED

4/27/22 J. DuBois

QUALITY
38
CHECKED



KESN: EASTON/NEWNAM FLD
EASTON, MD
SCALE: 1:100000
RNAV GPS RWY 4, AMDT 1B
NEW LNAV/VNAV CONTROLLING
OBSTACLE: 24-037662.

LNAV/VNAV/LNAV PFAF to KESN:RW04:AER ANTENNA (294)
24-037662