

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 11/05/2020	APWS Task ID: 3C863A04EB1844FABD989E0FF1775F08	APWS Project ID: BDEE043EEF1B427990760B821FB54345
Procedure: FIX ZERZO 3 MT US		Enroute: YES	Specialist: Hanby, William		Agreement Number:
Airport ID:	Airport Name:		Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			

Procedure Comments:
STANDALONE FIX.

Processed IAW Aircraft Operations Group (AJF-10) Memo, April 29, 2020
Subject: Flight Inspection Review Not Required

MITIGATE FDC 9/6091 - BIL TACAN UNUSABLE BEYOND 69 NM - NO BIL DME ESV TO ZERZO.

CONTACT MR. JOHN BORDY, IFP Team 2, Sub-Team B, AJV-A422 AT 405-954-0980.



8/14/20 J. DuBois