

Flight Procedures Cover Page	Task Action: Amendment	Task Type: IAP	Estimated Chart Date: 08/13/2020	APWS Task ID: 5AD5698DDF904D618D15F2AEA90AC988	APWS Project ID: 6CE7BCE1297C45D8B58699DA0DE73087
Procedure: RNAV (GPS) RWY 10 AMDT 0C		Enroute: NO	Specialist: Hazelton, John		Agreement Number:
Airport ID: KALB	Airport Name: ALBANY INTL		Airport City: ALBANY		State: NY
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments:</p> <p>P-NOTAM</p> <p>NEW CIRCLING TO MATCH EXISTING.</p> <p>PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.</p> <p>CONTACT: DAVID DANNER/MARLON ROBINSON AJV-A42 POC, 405.954.5077/3636.</p>					

QUALITY
15
CHECKED




QUALITY
10
CHECKED

WAAS CH 97523 W10A	APP CRS 101°	Rwy Idg 6780 TDZE 278 Apt Elev 285
--	------------------------	---

RNAV (GPS) RWY 10

ALBANY INTL (ALB)

⚠ Circling NA West of Rwy 1-19. DME/DME RNP-0.3 NA. Helicopter visibility reduction below $\frac{3}{4}$ SM NA.		MISSED APPROACH: Climb to 5000 direct SIMAY and on track 091° to WARUV and hold, continue climb-in-hold to 5000.		
D-ATIS 120.45	ALBANY APP CON 132.825 307.2	ALBANY TOWER 119.5 257.8	GND CON 121.7 348.6	CLNC DEL 127.50



NE-2: 05 DEC 2019 to 02 JAN 2020

NE-2: 05 DEC 2019 to 02 JAN 2020