

[Print](#)

Project Name: FDR RWY 35 VGSI DATA

Project Reason: RWY 35 PAPI relocation allows for removal of VGSI not coincident note on the approach. Update night landing chart note. Update chart planview note for arrivals at SPS VORTAC. Remove *LNAV only and asterisks from profile view.

Last Updated By: Timothy Johnson

Digitally signed by

DAVID DANNER

Last Updated At: 2024-07-03 16:27:53.837557

Sep 05, 2024

QUALITY
32
CHECKED

Status: Verified

!FDC 4/0640 FDR IAP FREDERICK RGNL, FREDERICK, OK. RNAV (GPS) RWY 35, ORIG-B... CHANGE NIGHT LANDING NOTE TO READ: CIRCLING RWY 3, 12, 17, 21, 30, NA AT NIGHT. CHANGE PLAINVIEW NOTE TO READ: PROCEDURE NA FOR ARRIVALS AT SPS VORTAC ON V404 EASTBOUND. DELETE PROFILE NOTE: *LNAV ONLY. DELETE ASTERISK IN PROFILE AT WEXAV AND VDP. DELETE PROFILE NOTE: VGSI AND RNAV GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.09/TCH 46). THIS IS RNAV (GPS) RWY 35, ORIG-C. 2407031627-PERM