

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 05/15/2025	APWS Task ID: 8C5E3100F7BB496698CB9D5119D17CDF	APWS Project ID: 98AF2FB1EBC240C39EF2D647153E73F9
Procedure: FIX BOSVE 1 OR US		Enroute: NO	Specialist: Patterson, Lawrence		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>8260-2 REVISION FOR THIRD PARTY SPECIALS AT 6S2.</div> <div>BOSVE, OR REV 1</div> <div>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.</div> <div>CONTACT: DON LANIER, AJV-A441 MANAGER, 405 954 8242.</div> <div>04/01/25: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 03/03/25.</div> <div>1. ADDED DME TO FIX TYPE.</div> <div>2. ADDED CONTROLLER LOW TO REQUIRED CHARTING.</div> <div>3. LATITUDE CHANGED FROM 440934.67 TO 440934.66.</div> <div>QUALITY 18 CHECKED</div>					