

[Print](#)

Project Name: ILS or LOC RWY 30L NOTE: FAM R-016 removal

Project Reason: ILS or LOC RWY 30L, Amdt 9E task required based on the project remarks "**** NOTE: FAM R-016 needs to be removed from the I/L RWY 30L - ESV to support its charting was disapproved and FAM was removed from the EBOPE 8260-2". Updated new FAS obstacle, Transmission Line 655 (4D) + 250 ROC + 50 AC = 955 (960) increased MDA/HAT 20 ft. Corrected TDZE data for rounding issue.

Last Updated By: Derek LaRue

Last Updated At: 2023-11-17 16:58:08.103072

Status: Verified 4/3266

Digitally signed by

RAKE MCGRAW

Jan 12, 2024

QUALITY
32
CHECKED

!FDC X/XXXX CPS IAP ST LOUIS DOWNTOWN, CAHOKIA/ST LOUIS, IL. ILS OR LOC RWY 30L, AMDT 9D... CHANGE TDZE TO READ 411. DELETE PLANVIEW R-016 FROM FARMINGTON (FAM) VORTAC TO (IF/IAF) EBOPE. S-ILS 30L DA 611 ALL CATS. S-LOC 30L MDA 960/HAT 549 ALL CATS, VIS CAT C 1 1/8. DELETE FAS OBSTACLE: 679 TREE 383202N/0900456W. CHART FAS OBSTACLE: 655 TRANSMISSION LINE (17- 063993) 383236N/0900509W. THIS IS ILS OR LOC RWY 30L, AMDT 9E. 2311171658-PERM