

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: Route	Estimated Chart Date: 08/07/2025	APWS Task ID: 922B95312F644A90959ACDCEAA407A65	APWS Project ID: DE6B89C5AA0E4E6A8826337D851F0062
Procedure: B27 RWO NDB, AK TO HHM NDB, AK		Enroute: YES	Specialist: Johnson, Raymond		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: AUB AND SMA Decommissioning AIRSPACE DOCKET # 22-AAL-26 AIRWAY STARTING POINT: WOODY ISLAND (RWO) NDB, AK: 574629.34N/1521928.51W. CONTACT: ALLAN WILL, TEAM 2 SUBTEAM-C MANAGER, 405.954.6102 06/12/25: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 02/12/25. 8260-2 FIX WOODY ISLAND (RWO) NDB. 1. FIX USE: ADDED PATTERN 1 TO SPECIAL IAP ILS Z OR LOC Z RWY 26 AT PADQ.</div> <div>QUALITY 18 CHECKED</div>					