

Flight Procedures Cover Page	Task Action: Amendment	Task Type: Segment	Estimated Chart Date: 10/05/2023	APWS Task ID: 9CEA020AFF82496E9C4317ACADDDFEA8	APWS Project ID: 6FC4561F0CC646E6ADF7852AF45B9C70
Procedure: J 70 MULLAN PASS (MLP) VOR/DME, ID TO DICKINSON (DIK) VORTAC, ND		Enroute: YES	Specialist: Johnsen, Daniel		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021, Subject: Guidance for Procedural Changes Requiring Flight Inspection/Validation.</div> <div>Airway starting point: MULLAN PASS (MLP) VOR/DME, ID 472724.85N/1153845.76W.</div> <div>Cancels NOTAMs FDC 2/0130, 2/0128, 2/0125, 2/9629, 2/0127, 2/0123, 2/0129, and 2/0126.</div> <div>Contact Allan Will, AJV-A423, 405-954-6103.</div> <div><div>QUALITY 32 CHECKED</div><div>Digitally signed by PABLO ORTIZ-JR May 18, 2023</div></div>					

