

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 10/07/2021	APWS Task ID: C4543BFED6274DA3BE888364908CEFF3	APWS Project ID: 8300708DF43246B1BBC194262F74A639
Procedure: ILS OR LOC RWY 29 AMDT 2A		Enroute: NO	Specialist: Johnsen, Daniel		Agreement Number:
Airport ID: KHAO			Airport City: HAMILTON		State: OH
Facility ID: RQF	Facility Type: ILS	Flight Inspection Remark Type: New FC Slot			
<p>Procedure Comments:</p> <p>Processed IAW Aircraft Operations Group (AJF-1000) Memo, dated June 4, 2020, Subject: Flight Inspection of New Controlling Obstacles.</p> <p>Abbreviated amendment using active data for KHAO airport and runways.</p> <p>Cancels NOTAM FDC 9/3630.</p> <p>Contact Jason Kretschmer, AJV-A421, 405-954-4019.</p> <div style="display: flex; justify-content: space-between; align-items: flex-end; margin-top: 20px;"> <div style="text-align: center;"> <p><i>Digitally signed by</i> JASON KRETSCHMER Jul 15, 2021</p> </div> <div style="text-align: right;"> <p><i>Digitally signed by</i> MARY MCDONALD Jun 28, 2021</p> </div> </div>					

QUALITY
26
CHECKED

QUALITY
12
CHECKED

LOC/DME I-RQF

109.75

Chan 34 (Y)

APP CRS

295°

Rwy Idg

5500

TDZE

619

Apt Elev

633

OLD

ILS or LOC RWY 29

BUTLER COUNTY RGNL-HOGAN FIELD (HAO)

ADF required. DME required for LOC only.

▽

Inop table does not apply to S-ILS 29. For inop ALS, increase S-LOC-29 Cat C/D visibility to 2½ SM. ARTHN fix minimums: for inop ALS, increase S-LOC 29 Cat C/D visibility to 1½ SM.

MALS

⏏

A4

MISSED APPROACH: Climb to 1600 then climbing right turn to 2600 direct HKF NDB and hold.

ASOS 121.425	CINCINNATI APP CON 121.0 254.25	CLNC DEL 126.25	UNICOM 123.05 (CTAF) 0
-----------------	------------------------------------	--------------------	---------------------------

ELEV 633		TDZE 619			
<div><div>1600</div><div>2600</div><div>HKF</div></div>		<div><div>ARTHN INT I-RQF 3.6</div><div>HOLGR INT I-RQF 7.1</div><div>One Minute Holding Pattern</div></div>			
*LOC only.		<div><div>115°</div><div>295°</div><div>2600</div><div>5100</div><div>GS 3.00° TCH 46</div></div>			
<div><div>1.4 NM</div><div>1.1 NM</div><div>3.5 NM</div></div>		<div><div>295° 6 NM from FAF</div><div>5500 X 100</div></div>			
CATEGORY	A	B	C	D	
S-ILS 29	819-¾		200 (200-¾)		
S-LOC 29	1440-¾ 821 (900-¾)	1440-1 821 (900-1)	1440-2	821 (900-2)	
CIRCLING	1440-1	807 (900-1)	1440-2½ 807 (900-2½)	1760-3 1127 (1200-3)	
ARTHN FIX MINIMUMS					
S-LOC 29	1120-¾ 501 (500-¾)	1120-1¼ 501 (500-1¼)			
CIRCLING	1160-1 527 (600-1)	1260-1 627 (700-1)	1300-1¾ 667 (700-1¾)	1760-3 1127 (1200-3)	
MIRL Rwy 11-29 0 REIL Rwys 11 and 29 0					
FAF to MAP 6 NM					
Knots	60	90	120	150	180
Min:Sec	6:00	4:00	3:00	2:24	2:00

HAMILTON, OHIO

Amtd 2 03JAN19

BUTLER COUNTY RGNL-HOGAN FIELD (HAO)

39°22'N-84°31'W

ILS or LOC RWY 29

