

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 10/02/2025	APWS Task ID: C57D052747CB4C7286172EFA7636D0AB	APWS Project ID: 59BDA3C3B73345FFA5B5EE08916951F5
Procedure: RNAV (GPS) RWY 5 AMDT 2D		Enroute: NO	Specialist: Hirst, Charles		Agreement Number:
Airport ID: KMSS			Airport City: MASSENA		State: NY
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>MSS 28 Day Review #25456 - RWY 5 VGSI TCH changed from 58.3 to 55.4 FT.</div> <div>P-NOTAM</div> <div>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION</div> <div>Delete VGSI not coincident note. Update backup altimeter note.</div> <div>For additional questions contact Robert Hamilton, Manager 405-954-4608</div> <div><div>QUALITY 41 CHECKED</div><div>QUALITY 16 CHECKED</div></div>					