

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 10/05/2023	APWS Task ID: CAF6758A5478421CB8B68100E96A540B	APWS Project ID: B9912B4CA92F4AC784B487CE93F28EE5
Procedure: FIX HOBES 2 AZ US		Enroute: NO	Specialist: Powell, Dan		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: ADMN 8260-2 PROJ TO MATCH WHAT IS CURRENTLY PUBLISHED ON CHARTS. MULTIPLE FIX PROJECT: HOBES, AZ REV 2; KEYKE, AZ REV 2; PYRIT, AZ REV 1; INW VTAC, AZ REV 23. CONTACT DAVE DANNER, AJV-A440 LEAD, 405-954-5077.</div> <div><div>QUALITY 32 CHECKED</div><div>Digitally signed by PABLO ORTIZ-JR Mar 17, 2023</div></div>					