


Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 11/05/2020	APWS Task ID: DA4D1B9401D04448AC17DA3401276ABF	APWS Request ID: BE987D99E3DF4B2B847386B86F9C77BE
Procedure: VOR OR TACAN RWY 17 AMDT 0D		Enroute: NO	Specialist: Boone-Walt, Rose		Agreement Number:
Airport ID: PHKO	Airport Name: ELLISON ONIZUKA KONA INTL AT KEAHOE	Airport City: KAILUA/KONA			State: HI
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments: PNOTAM CHART CIRCLING ICON PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, APRIL 29, 2020, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.</p> <p>CONTACT: JASON KRETSCHMER AJV-A421 LEAD: 405.954.4019</p>					

QUALITY
24
CHECKED

QUALITY
41
CHECKED



Airport ID	PHKO	FM9	No	SEGMENT	OBSTRUCTION	ELEV
Apt Name	ELLISON ONIZUKA KONA INTL AT KEAHOLE					
City	KAILUA/KONA	5		LNAY FINAL	TREE	169
State	HI					
Scale	1:100,000	8		CIRCLING A-E	SHIP	208
Proc ID	RNAV (GPS) RWY 35					
Amtd #	2	6		MISSED APPROACH LVL SFC	TRANSMISSION LINE	363