

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 07/13/2023	APWS Task ID: E999C8AE77AD47EE9A5AA1FD2C61A5EF	APWS Project ID: 7DD17E97D15E44AEA2367BFBCFB3F5D9
Procedure: FIX BANYO 15 AZ US		Enroute: NO	Specialist: Dumar, Ralph		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>REMARKS: SEPARATE -2 PROJECT FROM THE KDVT NEW CIRCLING P-NOTAM PROJECT. CONTACT RAKE MCGRAW (405) 954-8711</div> <div>QUALITY 49 CHECKED</div>					