

|   |                           |                                |                                     |   |  |
|---|---------------------------|--------------------------------|-------------------------------------|---|--|
| Flight Procedures Cover Page  | Task Action:<br>Amendment | Task Type:<br>FIX              | Estimated Chart Date:<br>05/18/2023 | APWS Task ID:<br>F470A3953A2F454B80D95814BC331F94 | APWS Project ID:<br>91C50D65A8F84D749D69855C14364C7E |
| Procedure:<br>FIX FAIRFIELD VORTAC 32 UT US   |                           | Enroute:<br>NO                 | Specialist:<br>Shaffer, Brian       |   | Agreement Number:                                    |
| Airport ID:   |                           |                                | Airport City:                       |   | State:   |
| Facility ID:  | Facility Type:            | Flight Inspection Remark Type: |                                     |   |  |
| <div>Procedure Comments:</div> <div>ADDING HOLDING &amp; SPECIAL USE COPTER FIX USE:<br/>COPTER RNAV (GPS) 16, ORIG   SANPETE VALLEY HOSPITAL (UT37)<br/>COPTER RNAV (GPS) 05, ORIG   HEBER VALLEY HOSPITAL (2UT4)<br/>COPTER RNAV (GPS) 27, ORIG, COPTER RNAV (GPS) 31, ORIG   RIVERTON HOSPITAL (3UT6)<br/>COPTER RNAV (GPS) 34, AMDT 1   PROMARY CHILDRENS MEDICAL CENTER (UT08)<br/>COPTER RNAV (GPS) 10, AMDT 1   UTAH VALLEY RGNL MEDICAL CENTER (UT51)<br/>COPTER RNAV (GPS) 34, AMDT 1   INTERMOUNTAIN MEDICAL CENTER (UT11)</div> <div>DATA ADDED IN SUPPORT OF PROCEDURES DEVELOPED BY THIRD PARTY DEVELOPERS.</div> <div>CONTACT DON LANIER (AJV-A441) (405)-954-8242</div> <div>QUALITY<br/>8<br/>CHECKED</div> |                           |                                |                                     |   |  |