

[Print](#)

Project Name: P08, AZ - NOTE ERRORS

Project Reason: NOTE ERRORS BECAUSE OF DOCUMENTATION ERRORS. Adding NoPT designation to initial from TFD VORTAC IAW 8260.19I 8-2-5.g(1). KP08 RWY 5 VGSI Angle/TCH changed from 3.00/40.0 to 3.00/44.6 on 8/13/20. VOR RWY 5 VDA 3.00/TCH 40.0. VGSI further changing to 3.00/48.6 on 12/2/21 - NOTAM to be updated if necessary. Adding VGSI not coincident note IAW 8260.19I 8-6-9.m(2).

Last Updated By: Anthony Cappabianco

Last Updated At: 2021-09-27 13:40:25.68879

Status: Verified **1/5936**

!FDC ~~XXXX~~ P08 IAP COOLIDGE MUNI, COOLIDGE, AZ. VOR RWY 5, AMDT 1... CHART PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT (VGSI ANGLE {ANGLE}/TCH {FEET}). ADD NOTE: TERMINAL ROUTE FROM TFD VORTAC TO WEMRU/TFD 9.02 DME (NOPT). THIS IS VOR RWY 5, AMDT 1A. 2109271340-PERM

Digitally signed by
CASIMIR L TABAKA
Nov 04, 2021

QUALITY
14
CHECKED