

Flight Procedures Cover Page	Task Action: Amendment	Task Type: SID	Estimated Chart Date: 01/30/2020	APWS Task ID: F5ADEE74F2A94711AB42F3F09E41ACEC	APWS Request ID: 4389363D941F40ECA866C513C07F3F36
Procedure: SID RIKKK (RNAV) FIVE DENVER CO KCFO		Enroute: YES	Specialist: Brandenburg, Phillip		Agreement Number:
Airport ID: KCFO	Airport Name: COLORADO AIR AND SPACE PORT	Airport City: DENVER			State: CO
Facility ID:	Facility Type:	Flight Inspection Remark Type:			

Procedure Comments:

APT NAME CHANGE, ID CHANGE FROM KFTG TO KCFO.

PENDING DATA USED.

PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED.

CONTACT ALLAN WILL 4059546103.

12/10/19: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 12/4/19.

1. 8260-15B, FIXES AND/OR NAVAIDS: REMOVED TAYOT.

12/18/19: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 12/4/19.

1. 8260-15B, CHANGED ROCKY MOUNTAIN METROPOLITAN DP ROUTE DESCRIPTION FROM ...EXPECT HIGHER ALTITUDE 10 MINUTES... TO ...EXPECT HIGHER FILED ALTITUDE 10 MINUTES...

2. CHANGED KFTG TO KCFO IN REMARKS.

APPROVED

By Steven M Barnett at 7:30 am, Dec 20, 2019

