



Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/08/2022	APWS Task ID: F97BA9305F9347CC91E735DB4839BD24	APWS Project ID: 5BC EE36AA2EE4D11B94C1D1C9D123B24
Procedure: VOR RWY 26L AMDT 1A		Enroute: NO	Specialist: Hanby, William		Agreement Number:
Airport ID: KPUB			Airport City: PUEBLO		State: CO
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<p>Procedure Comments: P-NOTAM ACTIVE DATA USED. DELETE CIRCLING CAT C LINE OF MINIMUM - NEW CIRCLING CAT C CONTROLLING OBSTACLE: TRAVERSE WAY (08-075140) 382031.65N/1043258.69W, 5275 MSL, (2C). 5275 + 300 (ROC) = 5575 (5580 ROUNDED). NEW CIRCLING CAT C SHOULD BE MDA 5580/HAA 851. CIRCLING MINIMA CAN NOT BE HIGHER THAN FAF ALTITUDE 5500 FT - CIRCLING CAT C REMOVED. PER FAAO 8260.19I, IMPLEMENTATION LETTER ATTACHMENT 7 - CIRCLING MINIMUMS MAY BE REMOVED BY P-NOTAM. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION THIS CANCELS FDC 1/5212. CONTACT MARK ADAMS: (405) 954-9946</p> <div style="text-align: right;">  5/26/22 J. DuBois </div> <div style="text-align: right; margin-top: 200px;">  Digitally signed by MARK D ADAMS Jun 14, 2022 </div>					