

**Federal Aviation
Administration**

Transmittal Letter 19-21

August 23, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10/10/2019	WA	Yakima	Yakima Air Terminal/Mcallister Field	9/7836	7/31/2019	ILS OR LOC RWY 27, Amdt 1

AIRAC Date: 10 OCTOBER 2019

FDC 9/7836 YKM IAP YAKIMA AIR TERMINAL/MCALLISTER FIELD, Yakima, WA. ILS OR LOC RWY 27, AMDT
1... ALTERNATE MINIMUMS: ILS: CAT A-D 700-2. THIS IS ILS OR LOC RWY 27, AMDT 1A. 1906200901-PERM