

**Federal Aviation
Administration**

Transmittal Letter 16-09

March 11, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
28-Apr-16	AZ	Douglas Bisbee	Bisbee Douglas Intl	5/8474	03/03/16	VOR/DME RWY 17, Amdt 6

AIRAC Date: 28 APRIL 2016

FDC 5/8474 DUG IAP BISBEE DOUGLAS INTL, DOUGLAS BISBEE, AZ. VOR/DME RWY 17, AMDT 6... DELETE NOTE:CIRCLING TO RWY 8 NA AT NIGHT.. DELETE NOTE:WHEN VGSI INOP CIRCLING TO RWY 26 NA AT NIGHT.. DELETE NOTE: WHEN VGSI INOP STRAIGHT-IN/CIRCLING RWY 17 NA AT NIGHT.. CHANGE THRE 4125 TO TDZE 4125. DELETE NOTE: VISIBILITY REDUCTION BY HELICOPTERS NA.. THIS IS VOR/DME RWY 17, AMDT 6A. 1511272020-PERM