

**Federal Aviation
Administration**

Transmittal Letter 08-17

July 11, 2008

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
25-Sept-08	AR	Little Rock	Adams Field	8/6150	07/07/08	VOR A, ORIG-A

AIRAC Date: 25 September 2008

FDC 8/6150 LIT FI/P ADAMS FIELD, LITTLE ROCK, AR. VOR A, ORIG- A...CHART
PROCEDURE TURN OUTBOUND, 2500 FT WITHIN 10NM OF LITTLE ROCK (LIT) VORTAC.
THIS IS VOR A, ORIG-B.